


<b>Glamorgan North-February</b> Cardiff Uni-Glamorgan    Conducted on <b>6th Feb, 2019</b> By <b>mike white</b>		
Inspection score	Failed items	Created actions
<b>90.91%</b>	<b>0</b>	<b>0</b>

Document No. <b>000003</b>
Audit Title <b>Glamorgan North-February</b>
Client / Site Unanswered
Conducted on <b>6th Feb, 2019</b> <b>08:42 AM GMT</b>
Prepared by <b>mike white</b>
Location <b>Cathays Park Bute Building King Edward VII Avenue Cardiff CF10 3NB Wales (51.48547728576409, -3.1814555674743357)</b>
Personnel Unanswered

# Audit

90.91%

Entrance/Reception <b>3</b> From 0 to 3
Ok
Unanswered
Meeting Rooms <b>3</b> From 0 to 3
Unanswered
Unanswered
Offices <b>3</b> From 0 to 3
Unanswered
Unanswered
Toilets <b>2</b> From 0 to 3
218a-Ok 2.40-Ok 2.01-Ok 1.09-Ok 1.07-Detail around plug hole 1.25a-Ok 0.07-Ok 0.09
Photos  Photo 1

<p>Stairwell/Corridors/Lifts</p> <p><b>3</b></p> <p>From 0 to 3</p>
Unanswered
Unanswered
<p>Classrooms</p> <p><b>3</b></p> <p>From 0 to 3</p>
Unanswered
Unanswered
<p>Kitchens/Coffee Shop</p> <p><b>3</b></p> <p>From 0 to 3</p>
2.38-Ok
Unanswered
<p>Seminar Rooms/Lecture Rooms</p> <p><b>3</b></p> <p>From 0 to 3</p>
Unanswered
Unanswered
<p>Chambers</p> <p><b>2</b></p> <p>From 0 to 3</p>
Ok
Unanswered
<p>IT Rooms</p> <p><b>3</b></p> <p>From 0 to 3</p>
Unanswered

Unanswered
Common Rooms/Committee Rooms <b>2</b> From 0 to 3
Room 1 and 2-Ok
Unanswered

Signatures


Solo Representative  6th Feb, 2019 7:11 PM GMT
Client Representative Unanswered



Photo 1